

# VALUES FOR MULTI-STAGE SETTING. BROILERS.

## TEMPERATURE °F / °C

99.7°F / 37.6°C

## HUMIDITY °F / °C

85°F - 84°F / 29.4 °C - 28.9°C / 54% - 51% (DEPENDING ON THE WEIGHT LOSS)

## CO<sub>2</sub>

0.35% - 0.40%

## VENTILATION %

30 - 35%

## TURNING

ON

## TURNING INTERVAL

EACH HOUR

## COOLING

WATER